

Scilab Textbook Companion for
Electric Machines - I
by M. Verma And V. Ahuja¹

Created by
Rishabh Narayan
B.Tech
Electrical Engineering
College OF Engineering Roorkee
College Teacher
Vivek Sharma
Cross-Checked by
Mukul R. Kulkarni

August 10, 2013

¹Funded by a grant from the National Mission on Education through ICT, <http://spoken-tutorial.org/NMEICT-Intro>. This Textbook Companion and Scilab codes written in it can be downloaded from the "Textbook Companion Project" section at the website <http://scilab.in>

Book Description

Title: Electric Machines - I

Author: M. Verma And V. Ahuja

Publisher: Vayu Education Of India, New Delhi

Edition: 1

Year: 2009

ISBN: 978-93-80097-03-9

Scilab numbering policy used in this document and the relation to the above book.

Exa Example (Solved example)

Eqn Equation (Particular equation of the above book)

AP Appendix to Example(Scilab Code that is an Appednix to a particular Example of the above book)

For example, Exa 3.51 means solved example 3.51 of this book. Sec 2.3 means a scilab code whose theory is explained in Section 2.3 of the book.

Contents

List of Scilab Codes	4
1 Introduction To Electrical Machines	9
2 DC Machines	13
3 Single Phase Transformers	52
4 Three Phase Transformers	81

List of Scilab Codes

Exa 1.9	Find the emf induced in the coil	9
Exa 1.10	Find the average value of emf induced in the coil . . .	10
Exa 1.11	Find the average emf induced in the coil and current through the coil	10
Exa 1.12	Find the average value of emf induced across the feild terminals	11
Exa 2.1	Find current delievered by each machine and terminal voltage	13
Exa 2.2	Find the load shared by two DC generators	14
Exa 2.3	Find the number of conductors	15
Exa 2.4	Find the generated voltage and armature current . . .	15
Exa 2.5	Find the shunt feild current and armature current and generated emf in armature and load resistance	16
Exa 2.6	Find the value of generated emf and armature current	17
Exa 2.7	Find the value of generated emf	18
Exa 2.8	Find the speed of generator	18
Exa 2.9	Find the armature current and generated emf and flux per pole	19
Exa 2.10	Find the load current and generated emf and flux per pole	20
Exa 2.11	Find the armature current and generated emf and num- ber of conductors of armature	21
Exa 2.12	Find the power absorbed by the load	22
Exa 2.13	Find the percentage reduction in speed	22
Exa 2.14	Find the speed	23
Exa 2.15	Find the Cu loss and iron and friction loss and torque	24
Exa 2.16	Find the Flux per pole and total number of conductors and torque	25

Exa 2.17	Find the Demagnetizing AT per pole and Cross magnetizing AT per pole and number of turns per pole	26
Exa 2.18	Find the current supplied by each generator and output voltage and output KW of each machine	27
Exa 2.19	Find the ratio of the speed as a generator to speed as a motor	28
Exa 2.20	Find the no load speed	29
Exa 2.21	Find the speed of motor	30
Exa 2.22	Find the speed of machine	30
Exa 2.23	Determine the total torque and useful torque and useful flux per pole and rotational losses and efficiency	31
Exa 2.24	Determine the speed and percentage change in torque	32
Exa 2.25	Determine the speed	33
Exa 2.26	Determine the speed	33
Exa 2.27	Determine the speed at half load and 125 percent full load	34
Exa 2.28	Determine the value of resistance	35
Exa 2.29	Determine the value of additional resistance at starting and at 1000rpm	36
Exa 2.30	Determine the speed at full load and speed at double full load and stalling torque in terms of full load torque	36
Exa 2.31	Determine the resistance to be inserted in series	37
Exa 2.32	Determine the resistance to be inserted in series	38
Exa 2.33	Determine the output and efficiency when input current is 20A and 100A	39
Exa 2.34	Determine the no load speed and Full load speed and Speed Regulation	40
Exa 2.35	Determine the no load speed and Percentage reduction in flux per pole	41
Exa 2.36	Determine the full load speed and Speed regulation and HP rating and Full load efficiency	42
Exa 2.37	Determine the speed Torque and Efficiency	43
Exa 2.38	Determine the efficiency and power input	44
Exa 2.39	Determine the efficiency armature current and max efficiency	45
Exa 2.40	Calculate the Speed at full load and developed torque and Shaft power and Efficiency	46

Exa 2.41	Calculate the value of external resistance when the load torque is independent of speed and when the load torque is proportional to speed and the load torque varies as square of the speed	47
Exa 2.43	Find the efficiency of the motor	48
Exa 2.44	Find the armature voltage drop	49
Exa 2.45	Find the no load speed	49
Exa 2.46	Find the percentage reduction in field flux and value of additional resistance	50
Exa 2.47	Find the new speed as a percentage of the original speed	51
Exa 3.1	Determine the number of turns of primary and secondary windings and emf per turn	52
Exa 3.2	Determine the number of turns of primary and secondary windings and cross section area of the core . .	53
Exa 3.3	Determine the number of turns of primary and secondary windings	53
Exa 3.4	Determine the Secondary voltage current flowing through windings and max value of flux	54
Exa 3.5	Determine the No load power factor iron loss component of current and magnetising component of current . . .	55
Exa 3.6	Determine the No load input power magnetising component of current and no load power factor	56
Exa 3.7	Determine the Equivalent resistance leakage reactances and impedance referred to high voltage side and Equivalent resistance leakage reactances and impedance referred to high voltage side and Total copper loss of transformer	57
Exa 3.8	Find the equivalent circuit parameters referred to primary side	58
Exa 3.9	Find the readings of transformers when it is connected for OC test and SC test	59
Exa 3.10	Find the equivalent circuit parameters of the transformer referred to LV side and also calculate the secondary voltage	60
Exa 3.11	Find the equivalent circuit parameters of the transformer referred to LV side and also calculate the efficiency . .	62

Exa 3.12	Calculate Efficiency of transformer Load KVA at which max efficiency occurs and max efficiency and voltage regulation	63
Exa 3.13	Determine the KVA rating of auto transformer with additive and subtractive polarity also find the efficiency at full load and unity power factor	64
Exa 3.14	Calculate the parameters referred to LV Side and also find the voltage regulation at full load and efficiency of transformer at full load and half load	65
Exa 3.15	Calculate the circuit parameters referred to LV Side and also calculate the regulation and efficiency of transformer at full load and half load	67
Exa 3.16	Find the efficiency of transformer at full load and 75 percent of full load	68
Exa 3.17	Determine the Load at which max efficiency occurs and value of max efficiency and New core loss and Cu loss	69
Exa 3.18	Calculate the secondary current at which max efficiency will occur and also calculate the max efficiency	70
Exa 3.19	Find the iron loss copper loss at full load Load KVA at which maximum efficiency occurs and maximum efficiency of transformer	71
Exa 3.22	Calculate Efficiency at full load and half load	72
Exa 3.23	Calculate the core loss and copper loss and also find the value of load current at which max efficiency will be attained	73
Exa 3.24	Calculate the efficiency of the transformer at 75 percent of full load and maximum efficiency	74
Exa 3.25	Calculate the efficiency of the transformer on full load and half load at unity power factor	75
Exa 3.26	Find the voltage regulation	76
Exa 3.27	Calculate the percentage resistance and reactance drops and the percentage of full load at which max efficiency will occur	76
Exa 3.28	Find the voltage regulation	77
Exa 3.29	Calculate the value of iron loss and copper loss which will give max efficiency and also the max efficiency	78
Exa 3.30	Find the Efficiency and voltage regulation of transformer	79
Exa 4.1	Find the value of line current	81

Exa 4.2	Find the value of line current	81
Exa 4.3	Determine the efficiency of transformer	82
Exa 4.4	Find the value of line voltage and line current and output	83
Exa 4.5	Find the Efficiency	84
Exa 4.6	Find the percentage resistance and reactance drop and efficiency and voltage regulation	85
Exa 4.7	Determine the KVA Load and Percentage rated load and Total KVA Rating and Ratio of star bank to delta bank transformer rating and percentage increase in load	86
Exa 4.8	Determine the Current flowing in various sections and Power transformed and Power conducted directly . . .	87

Chapter 1

Introduction To Electrical Machines

Scilab code Exa 1.9 Find the emf induced in the coil

```
1 //Chapter:1:Introduction to electrical Machines
2 //Caption:Find the emf induced in the coil
3 //Exa:1.9
4 clc;
5 clear;
6 close;
7 N=800; //No. of turns
8 Phy_1=2000*10^-6; //In Webers
9 Phy_2=1000*10^-6; //In Webers
10 t=0.1; //in seconds
11 e=N*(Phy_1-Phy_2)/t;
12 disp(e, 'Emf induced in the coil (in volts)=')
```

Scilab code Exa 1.10 Find the average value of emf induced in the coil

```
1 //Caption:Find the average value of emf induced in
   the coil
2 //Exa:1.10
3 clc;
4 clear;
5 close;
6 N=1000; //No. of turns
7 Phy_1=2000*10^-6; //In Webers
8 //On reversal of current
9 Phy_2=2000*10^-6; //In Webers
10 t=0.2; //in seconds
11 e=N*(Phy_1-(-Phy_2))/t;
12 disp(e, 'Average value of emf induced in the coil (in
   volts)=')
```

Scilab code Exa 1.11 Find the average emf induced in the coil and current through the coil

```
1 //Caption:Find the (1) average emf induced in the
   coil (2) current through the coil
2 //Exa:1.11
3 clc;
```

```

4 clear;
5 close;
6 N=300; //No. of turns
7 R=60; //resistance in ohms
8 Phy_1=2*10^-3; //In Webers
9 Phy_2=3*10^-3; //In Webers
10 t=0.2; //in seconds
11 e=N*(Phy_2-Phy_1)/t;
12 disp(e, '(1) Average emf induced in the coil (in
    volts)=');
13 i=e/R;
14 disp(i, '(2) Current through the coil (in Amperes)=')

```

Scilab code Exa 1.12 Find the average value of emf induced across the field terminals

```

1 //Caption:Find the average value of emf induced
    across the field terminals
2 //Exa:1.12
3 clc;
4 clear;
5 close;
6 P=4; //no of poles
7 N=4*250; //No. of turns
8 Phy_1=40*P*10^-3; //In Webers
9 Phy_2=5*P*10^-3; //In Webers
10 t=0.1; //in seconds
11 e=N*(Phy_1-Phy_2)/t;
12 disp(e, 'average value of emf induced across the
    field terminals (in volts)=')

```

Chapter 2

DC Machines

Scilab code Exa 2.1 Find current delivered by each machine and terminal voltage

```
1 //Caption:Find (a)current delivered by each machine
   and (b)terminal voltage
2 //Exa:2.1
3 clc;
4 clear;
5 close;
6 //for 50kw generator
7 I_1=50*1000/500;//full load current in ampere
8 V_1=0.06*500;//full load voltage drop in volts
9 V_1pi=V_1/I_1;//voltage drop per ampere of current
   supply in volts/ampere
10 //for 100kw generator
11 I_2=100*1000/500;//full load current in ampere
12 V_2=0.04*500;//full load voltage drop in volts
13 V_2pi=V_2/I_2;//voltage drop per ampere of current
   supply in volts/ampere
14 i_1=250/(1+(V_1pi/V_2pi));//in amperes
15 i_2=250/(1+(V_2pi/V_1pi));//in amperes
16 disp(i_1,'(a) Current delivered in 50kw generator (
   in amperes)=');
```

```

17 disp(i_2, '      Current delievered in 100kw generator
      (in amperes)=');
18 V_t=500-V_1pi*i_1;//in volts
19 disp(V_t, '(b) Terminal voltage (in volts)=')

```

Scilab code Exa 2.2 Find the load shared by two DC generators

```

1 //Caption:Find the load shared by two DC generators
2 //Exa:2.2
3 clc;
4 clear;
5 close;
6 E_g1=120;//in volts
7 E_g2=115;//in volts
8 R_a1=0.05;//armature winding resistance of first
      generator (in ohms)
9 R_a2=0.04;//armature winding resistance of second
      generator (in ohms)
10 R_f1=20;//feild winding resistance of first
      generator (in ohms)
11 R_f2=25;//feild winding resistance of second
      generator (in ohms)
12 P=25000;//in watts
13 V_t=(5275+sqrt((5275^2)-(4*45.09*25000)))/(2*45.09);
      //terminal voltage in volts
14 I_1=(E_g1-(V_t*(1+(R_a1/R_f1))))/R_a1;//in amperes
15 I_2=(E_g2-(V_t*(1+(R_a2/R_f2))))/R_a2;//in amperes
16 P_1=V_t*I_1/1000;//in kilo watts
17 P_2=V_t*I_2/1000;//in kilo watts
18 disp(P_1, 'Power shared by generator -1(in Kilo Watts)
      = ');

```

```
19 disp(P_2, 'Power shared by generator -2(in Kilo Watts)
    = ');
```

Scilab code Exa 2.3 Find the number of conductors

```
1 //Caption:Find the number of conductors
2 //Exa:2.3
3 clc;
4 clear;
5 close;
6 P=8;//no. of poles
7 A=8;
8 Phy=40*10^-3;//flux in weber
9 N=500;//speed in rpm
10 E_g=250;//no-load voltage in volts
11 Z=(E_g*60*A)/(P*N*Phy);
12 disp(Z, 'Number of conductors=')
```

Scilab code Exa 2.4 Find the generated voltage and armature current

```
1 //Caption:Find the generated voltage and armature
  current
2 //Exa:2.4
3 clc;
4 clear;
```



```

5  close;
6  V_t=300; //in volts
7  V_b=1; //voltage drop per brush in volts
8  I=200; //in amperes
9  R_f=200; //shunt feild winding resistance in ohms
10 R_a=0.05; //armature winding resistance in ohms
11 R_se=0.04; //Series feild winding resistance in ohms
12 I_f=V_t/R_f; //in amperes
13 I_a=I+I_f; //in amperes
14 E_g=V_t+(R_a+R_se)*I_a+(2*V_b);
15 disp(E_g, 'Value of generated voltage (in volts)=');
16 disp(I_a, 'Value of armature current (in Ampers)=')

```

Scilab code Exa 2.5 Find the shunt feild current and armature current and generated emf in armature and load resistance

```

1  //Caption:Find the (a)shunt feild current (b)
    armature current (c)generated emf in armature (d)
    load resistance
2  //Exa:2.5
3  clc;
4  clear;
5  close;
6  V_t=250; //in volts
7  I=195; //in amperes
8  R_f=50; //shunt feild winding resistance in ohms
9  R_a=0.05; //armature winding resistance in ohms
10 I_f=V_t/R_f; //in amperes
11 I_a=I+I_f; //in amperes
12 E_g=V_t+(R_a*I_a);
13 R_L=V_t/I;

```

```

14 disp(I_f, '(a) Value of shunt feild current (in
    Amperes)=')
15 disp(I_a, '(b) Value of armature current (in Amperes)
    =')
16 disp(E_g, '(c) Value of generated voltage (in volts)=
    ');
17 disp(R_L, '(d) Value of load resistance (in ohms)=')

```

Scilab code Exa 2.6 Find the value of generated emf and armature current

```

1 //Caption:Find the value of generated emf and
    armature current
2 //Exa:2.6
3 clc;
4 clear;
5 close;
6 V_t=250;//in volts
7 V_AC=V_t;
8 V_b=1;//voltage drop per brush in volts
9 I=40;//in amperes
10 R_f=100;//shunt feild winding resistance in ohms
11 R_a=0.05;//armature winding resistance in ohms
12 R_se=0.04;//series feild winding resistance in ohms
13 V_BC=V_AC+I*R_se;//in volts
14 I_f=V_BC/R_f;//in amperes
15 I_a=I+I_f;//in amperes
16 E_g=V_BC+(R_a*I_a)*(2*V_b);
17 disp(I_a, ' Value of armature current (in Amperes)=')
    ;
18 disp(E_g, ' Value of generated voltage (in volts)=');

```

Scilab code Exa 2.7 Find the value of generated emf

```
1 //Caption:Find the value of generated emf
2 //Exa:2.7
3 clc;
4 clear;
5 close;
6 P=8;//no. of poles
7 A=8;
8 Z=760;//no.of conductors
9 Phy=35*10^-3;//flux in weber
10 N=500;//speed in rpm
11 E_g=(P*N*Phy*Z)/(60*A);
12 disp(E_g, 'Value of generated emf (in volts)=')
```

Scilab code Exa 2.8 Find the speed of generator

```
1 //Caption:Find the speed of generator
2 //Exa:2.8
3 clc;
4 clear;
5 close;
6 P=8;//no. of poles
7 S=70;//no. of slots
```

```

8 C=22; //conductors per slot
9 A=8;
10 D=0.48; //in meter
11 Z=S*C; //no.of conductors
12 r=0.64; //ratio of pole arc to pole pitch
13 l=0.28; //length of pole shoe in meter
14 B=0.32; //air gap flux density in weber/meter^2
15 E_g=400; //in volts
16 Pole_arc=r*pi*D/P; //in meter
17 Ao=Pole_arc*l; //Area of pole shoe in meter
18 Phy=Ao*B; //in weber
19 N=E_g*60*A/(Phy*Z*P);
20 disp(N, 'Speed of generator (in rpm)=')

```

Scilab code Exa 2.9 Find the armature current and generated emf and flux per pole

```

1 //Caption:Find the (a)armature current (b)generated
   emf (c)flux/pole
2 //Exa:2.9
3 clc;
4 clear;
5 close;
6 V_t=200; //in volts
7 P=4; //no. of poles
8 A=2;
9 Z=676; //no.of conductors
10 R_L=10; //load resistance in ohms
11 R_a=0.34; //armature winding resistance in ohms
12 R_f=100; //feild winding resistance in ohms
13 N=600; //speed in rpm

```

```

14 I_f=V_t/R_f;//in amperes
15 I=V_t/R_L;//in amperes
16 I_a=I+I_f;
17 E_g=V_t+I_a*R_a;
18 Phy=E_g*60*A/(P*N*Z);
19 disp(I_a, '(a) Armature current (in amperes)=');
20 disp(E_g, '(b) Generated emf (in volts)=');
21 disp(Phy*1000, '(c) flux/pole (in mili weber)=');

```

Scilab code Exa 2.10 Find the load current and generated emf and flux per pole

```

1 //Caption:Find the (a)load current (b)generated emf
   (c)flux/pole
2 //Exa:2.10
3 clc;
4 clear;
5 close;
6 V_t=250;//in volts
7 P=6;//no. of poles
8 A=P;
9 Z=700;//no.of conductors
10 R_a=0.04;//armature winding resistance in ohms
11 R_f=100;//feild winding resistance in ohms
12 N=1000;//speed in rpm
13 I_f=V_t/R_f;//in amperes
14 I_a=7.2/R_a;//in amperes
15 I=I_a-I_f;//in amperes
16 E_g=V_t+I_a*R_a;
17 Phy=E_g*60*A/(P*N*Z);
18 disp(I, '(a) Load current (in amperes)=');

```

```
19 disp(E_g, '(b) Generated emf (in volts)=');
20 disp(Phy*1000, '(c) flux/pole (in mili weber)=');
```

Scilab code Exa 2.11 Find the armature current and generated emf and number of conductors of armature

```
1 //Caption:Find the (a)armature current (b)generated
   emf (c) no. of conductors of armature
2 //Exa:2.11
3 clc;
4 clear;
5 close;
6 P_o=22000;//power in watts
7 V_t=220;//in volts
8 V_b=1;//per brush drop in volts
9 P=4;//no. of poles
10 A=2;
11 R_se=0.04;//series resistance in ohms
12 R_a=0.05;//armature winding resistance in ohms
13 R_f=110;//feild winding resistance in ohms
14 Phy=7.8*10^-3;//in weber
15 N=1000;//speed in rpm
16 I=P_o/V_t;//in amperes
17 I_f=V_t/R_f;//in amperes
18 I_a=I+I_f;
19 E_g=V_t+I_a*(R_a+R_se)+2*V_b;
20 Z=E_g*60*A/(Phy*N*P)
21 disp(I_a, '(a) Armature current (in amperes)=');
22 disp(E_g, '(b) Generated emf (in volts)=');
23 disp(Z, '(c) No. of conductors of armature=');
```

Scilab code Exa 2.12 Find the power absorbed by the load

```
1 //Caption:Find the power absorbed by the load
2 //Exa:2.12
3 clc;
4 clear;
5 close;
6 P=6;//no. of poles
7 A=2;
8 Z=350;//no. of conductors
9 R_a=0.8;//armature winding resistance in ohms
10 R_f=120;//feild winding resistance in ohms
11 Phy=0.02;//in weber
12 N=1000;//speed in rpm
13 R_L=12;//load resistance in ohms
14 E_g=Phy*N*Z*P/(60*A);//emf induced in volts
15 V_t=E_g/(1+((1/R_f)+(1/R_L))*R_a);
16 I_L=V_t/R_L;//in amperes
17 P_o=V_t*I_L;//in watts
18 disp(P_o,'Power absorbed by the load (in watts)=')
```

Scilab code Exa 2.13 Find the percentage reduction in speed

```
1 //Caption:Find the percentage reduction in speed
```

```

2 //Exa:2.13
3 clc;
4 clear;
5 close;
6 P1=200*10^3; //initial load in watts
7 P2=125*10^3; //final load in watts
8 V_t=250; //in volts
9 V_b=2; //total brush drop in volts
10 P=6; //no. of poles
11 R_a=0.015; //armature winding resistance in ohms
12 I_g1=P1/V_t; //in amperes
13 I_a1=I_g1; //in amperes
14 E_g1=V_t+I_a1*R_a+V_b; //in volts
15 I_g2=P2/V_t; //in amperes
16 I_a2=I_g2; //in amperes
17 E_g2=V_t+I_a2*R_a+V_b; //in volts
18 //since E_g is directly proportional to N
19 //therefore ,E_g1/E_g2=N_1/N_2
20 r=E_g2/E_g1;
21 reduction=(1-r)*100;
22 disp(reduction, 'Percentage reduction in speed (%)=')

```

Scilab code Exa 2.14 Find the speed

```

1 //Caption:Find the speed
2 //Exa:2.14
3 clc;
4 clear;
5 close;
6 V_t=400; //in volts
7 V_b=2; //total brush drop in volts

```



```

8 R_a=0.12; //armature winding resistance in ohms
9 N1=1000; //speed in rpm
10 I_a1=150; //in amperes
11 I_a2=100; //in amperes
12 R_L=V_t/I_a1; //load resistance in ohms
13 E_g1=V_t+I_a1*R_a+V_b; //in volts
14 V_to=R_L*I_a2; //in volts
15 E_g2=ceil (V_to+I_a2*R_a+V_b); //in volts
16 //Since E_g is directly proportional to N
17 //therefore ,E_g1/E_g2=N1/N2
18 N2= N1*E_g2/E_g1; //in rpm
19 disp(ceil(N2), 'Speed (in rpm)=')

```

Scilab code Exa 2.15 Find the Cu loss and iron and friction loss and torque

```

1 //Caption:Find the (a)Cu-loss (b)iron and friction
  loss (c) torque
2 //Exa:2.15
3 clc;
4 clear;
5 close;
6 P_o=25000; //output power in watts
7 V_t=250; //in volts
8 R_se=0.05; //series resistance in ohms
9 R_a=0.04; //armature winding resistance in ohms
10 R_f=50; //shunt feild winding resistance in ohms
11 Eff=0.89; //efficiency
12 N=1000; //speed in rpm
13 I=P_o/V_t; //in amperes
14 I_f=V_t/R_f; //in amperes

```

```

15 I_a=I+I_f;
16 P_cu=R_a*I_a^2+R_se*I_a^2+R_f*I_f^2; //copper loss in
    watts
17 disp(P_cu, '(a) Cu-loss (in watts)=');
18 P_i=P_o/Eff; //input power in watts
19 P_L=P_i-P_o; //total losses in watts
20 P_fric=P_L-P_cu;
21 disp(P_fric, '(b) Iron and friction loss (in watts)=');
    );
22 T=P_i*60/(2*%pi*N);
23 disp(T, '(c) Torque (in N-m)=')

```

Scilab code Exa 2.16 Find the Flux per pole and total number of conductors and torque

```

1 //Caption:Find the (a)Flux per pole (b)total number
    of conductors (c) torque
2 //Exa:2.16
3 clc;
4 clear;
5 close;
6 I_a=50; //in amperes
7 P=6; //no.of poles
8 E_g=200; //in volts
9 N=1500; //speed in rpm
10 A=6;
11 L=0.25; //in meter
12 d=0.2; //in meter
13 B=0.9; //in tesla
14 Theta=360/P; //angle subtended by pole shoe in
    degrees

```

```

15 l=%pi*L*Theta/360;//arc length of pole shoe in meter
16 area=l*d;//in meter^2
17 Phy=B*area;
18 disp(Phy, '(a) Flux per pole (in Weber)=');
19 Z=ceil(E_g*60/(Phy*N));
20 disp(Z, '(b) Total no. of conductors=');
21 T=9.55*E_g*I_a/N;
22 disp(T, '(c) Torque (in Newton-meter)=')

```

Scilab code Exa 2.17 Find the Demagnetizing AT per pole and Cross magnetizing AT per pole and number of turns per pole

```

1 //Caption:Find the (a)Demagnetizing AT per pole (b)
   Cross magnetizing AT per pole (c) number of turns
   per pole
2 //Exa:2.17
3 clc;
4 clear;
5 close;
6 P=40000;//in watts
7 E_g=400;//in volts
8 A=4;
9 Pole=4;
10 Z=2*30*12;//no. of conductors
11 theta_m=10;//in degrees
12 I_a=P/E_g;//armature current in amperes
13 I=I_a/A;//current in each conductor in amperes
14 AT_d=Z*I*theta_m/360;
15 disp(AT_d, '(a) Demagnetizing Ampere Turns per pole='
   );
16 AT_cm=Z*I*((1/(2*Pole))-(theta_m/360));

```

```

17 disp(AT_cm, '(b) Cross magnetizing Ampere Turns per
    pole=');
18 n=Z*I*0.8/(2*Pole*100);
19 disp(n, '(c) Number of turns per pole=')

```

Scilab code Exa 2.18 Find the current supplied by each generator and output voltage and output KW of each machine

```

1 //Caption:Find the (a) current supplied by each
    generator (b) output voltage (c) output KW of each
    machine
2 //Exa:2.18
3 clc;
4 clear;
5 close;
6 V_t1=280; //terminal voltage of generator-1 in volts
7 V_n11=240; //no-load voltage of generator-1 in volts
8 V_t2=300; //terminal voltage of generator-2 in volts
9 V_n12=240; //no-load voltage of generator-2 in volts
10 I_s1=40; //supply current to generator-1 in amperes
11 I_s2=50; //supply current to generator-2 in amperes
12 V_d1=V_t1-V_n11; //voltage drop for generator-1 in
    volts
13 V_d2=V_t2-V_n12; //voltage drop for generator-2 in
    volts
14 V_d1_pa=V_d1/I_s1; //voltage drop per ampere for
    generator-1 in volts/ampere
15 V_d2_pa=V_d2/I_s2; //voltage drop per ampere for
    generator-2 in volts/ampere
16 I_2=(20+60)/(V_d1_pa+V_d2_pa); //in amperes
17 I_1=60-I_2; //in amperes

```

```

18 disp(I_1, '(a) Current supplied by generator -1(in
    amperes)=');
19 disp(I_2, '(a) Current supplied by generator -2(in
    amperes)=');
20 V_1=V_t1-(V_d1_pa*I_1); //in volts
21 V_2=V_t2-(V_d2_pa*I_2); //in volts
22 disp(V_1, '(b) Output voltage of generator -1(in volts
    )=');
23 disp(V_2, '(b) Output voltage of generator -2(in volts
    )=');
24 P_1=V_1*I_1/1000; //in kilo watts
25 P_2=V_2*I_2/1000; //in kilo watts
26 disp(P_1, '(c) Output KW of generator -1(in Kilo watts
    )=');
27 disp(P_2, '(c) Output KW of generator -2(in Kilo watts
    )=');

```

Scilab code Exa 2.19 Find the ratio of the speed as a generator to speed as a motor

```

1 //Caption:Find the ratio of the speed as a generator
    to speed as a motor
2 //Exa:2.19
3 clc;
4 clear;
5 close;
6 V=250; //in volts
7 I_L=80; //in amperes
8 R_a=0.12; //in ohms
9 R=100; //in ohms
10 I_f=V/R; //in amperes

```

```

11 I_a1=I_L+I_f;//in amperes (generator)
12 E_1=V+(I_a1*R_a);//in volts (generator)
13 I_a2=I_L-I_f;//in amperes (motor)
14 E_2=V-(I_a2*R_a);//in volts (motor)
15 Ratio=E_1/E_2;
16 disp(Ratio,'Ratio of speed as a generator to speed
    as motor=')

```

Scilab code Exa 2.20 Find the no load speed

```

1 //Caption:Find the no load speed
2 //Exa:2.20
3 clc;
4 clear;
5 close;
6 V=200;//in volts
7 I_a0=2;//in amperes
8 R_a=0.4;//in ohms
9 I_a1=50;//in amperes
10 N_1=1200;//in rpm
11 E_0=V-(I_a0*R_a);//in volts
12 E_1=V-(I_a1*R_a);//in volts
13 N_0=N_1*(E_0/E_1);//in rpm
14 disp(N_0,'No-load speed (in rpm)=')

```

Scilab code Exa 2.21 Find the speed of motor

```
1 //Caption:Find the speed of motor
2 //Exa:2.21
3 clc;
4 clear;
5 close;
6 V=250;//in volts
7 I_L1=5;//in amperes
8 R_a=0.2;//in ohms
9 R_f=250;//in ohms
10 I_f=V/R_f;//in amperes
11 I_a1=I_L1-I_f;//in amperes
12 I_L2=50;//in amperes
13 I_a2=I_L2-I_f;//in amperes
14 N_1=1000;//in rpm
15 E_2=V-(I_a2*R_a);//in volts
16 E_1=V-(I_a1*R_a);//in volts
17 N_2=N_1*(E_2/E_1);//in rpm
18 disp(N_2,'speed of motor (in rpm)=')
```

Scilab code Exa 2.22 Find the speed of machine

```
1 //Caption:Find the speed of machine
2 //Exa:2.22
3 clc;
4 clear;
5 close;
6 V=250;//in volts
7 P_i=50*10^3;//in watts
8 I_L1=P_i/V;//in amperes
```

```

9 R_a=0.02; //in ohms
10 R_f=50; //in ohms
11 I_f=V/R_f; //in amperes
12 I_a1=I_L1+I_f; //in amperes
13 I_L2=P_i/V; //in amperes
14 I_a2=I_L2-I_f; //in amperes
15 N_1=400; //in rpm
16 E_2=V-(I_a2*R_a)-(2*1); //in volts
17 E_1=V+(I_a1*R_a)+(2*1); //in volts
18 N_2=int(N_1*(E_2/E_1)); //in rpm
19 disp(N_2, 'speed of motor (in rpm)=')

```

Scilab code Exa 2.23 Determine the total torque and useful torque and useful flux per pole and rotational losses and efficiency

```

1 //Caption:Determine the (a) total torque(b) useful
   torque(c) useful flux per pole(d) rotational losses
   (e) efficiency
2 //Exa:2.23
3 clc;
4 clear;
5 close;
6 P=4; //no of poles
7 Z=560; //no of conductors
8 A=2;
9 V=250; //in volts
10 P_o=10*10^3; //in watts
11 R_a=0.2; //in ohms
12 I_f=1; //in amperes
13 I_a=60; //in amperes
14 N=1000; //in rpm

```



```

15 V_b=1*2//in volts
16 E=V-(I_a*R_a)-V_b;//in volts
17 T=60*E*I_a/(2*%pi*N);//in Newton-meter
18 disp(T,'(a) Total torque (in Newton-meter)=');
19 T_useful=P_o*60/(2*%pi*N);
20 disp(T_useful,'(b) Useful torque (in Newton-meter)=');
21 Phy=60*E*A/(N*P*Z);
22 disp(Phy,'(c) Useful flux per pole (in Weber)=');
23 P_d=(V*I_a)-((I_a^2)*R_a)-(V_b*I_a);//in Watts
24 P_rot=P_d-P_o;
25 disp(P_rot,'(d) Rotational losses (in Watts)=');
26 P_i=V*(I_a+I_f);//in Watts
27 Eff=P_o*100/P_i;
28 disp(Eff,'(e) Efficiency (in %)=');

```

Scilab code Exa 2.24 Determine the speed and percentage change in torque

```

1 //Caption:Determine the speed and percentage change
  in torque
2 //Exa:2.24
3 clc;
4 clear;
5 close;
6 V=460;//in volts
7 R_a=0.8;//in ohms
8 I_a1=40;//in amperes
9 I_a2=30;//in amperes
10 N_1=500;//in rpm
11 E_1=V-(I_a1*R_a);//in volts
12 E_2=V-(I_a2*R_a);//in volts

```

```

13 N_2=int(E_2*I_a1*N_1/(E_1*I_a2));
14 disp(N_2,'Speed (in rpm)=');
15 ratio=(I_a2/I_a1)^2;
16 T_c=(1-ratio)*100;
17 disp(T_c,'Percentage change in torque=')

```

Scilab code Exa 2.25 Determine the speed

```

1 //Caption:Determine the speed
2 //Exa:2.25
3 clc;
4 clear;
5 close;
6 V=220;//in volts
7 R_a=0.1;//in ohms
8 I_a1=100;//in amperes
9 I_a2=sqrt(I_a1^2/2);//in amperes
10 N_1=800;//in rpm
11 E_1=V-(I_a1*R_a);//in volts
12 E_2=V-(I_a2*R_a);//in volts
13 N_2=int(E_2*I_a1*N_1/(E_1*I_a2));
14 disp(N_2,'Speed (in rpm)=');

```

Scilab code Exa 2.26 Determine the speed

```

1 //Caption:Determine the speed
2 //Exa:2.26
3 clc;
4 clear;
5 close;
6 V=250;//in volts
7 R_a=0.25;//in ohms
8 I_a1=50;//in amperes
9 I_a2=I_a1/0.9;//in amperes
10 N_1=750;//in rpm
11 E_1=V-(I_a1*R_a);//in volts
12 E_2=V-(I_a2*R_a);//in volts
13 N_2=int(E_2*N_1/(E_1*0.9));
14 disp(N_2,'Speed (in rpm)=');

```

Scilab code Exa 2.27 Determine the speed at half load and 125 percent full load

```

1 //Caption:Determine the speed (a)at half load (b)125
  % full load
2 //Exa:2.27
3 clc;
4 clear;
5 close;
6 V=120;//in volts
7 V_b=3;//in volts
8 R_a=0.2;//in ohms
9 R_f=60;//in ohms
10 I_L1=40;//in amperes
11 I_f=V/R_f;//inn amperes
12 I_a1=I_L1-I_f;//in amperes

```

```

13 N_1=1800; //in rpm
14 E_1=V-(I_a1*R_a)-V_b; //in volts
15 I_L2=I_L1/2;
16 I_a2=I_L2-I_f;
17 E_2=V-(I_a2*R_a)-V_b; //in volts
18 N_2=int(E_2*N_1/E_1);
19 disp(N_2, '(a) Speed at half load(in rpm)=');
20 I_L3=I_L1*1.25;
21 I_a3=I_L3-I_f;
22 E_3=V-(I_a3*R_a)-V_b; //in volts
23 N_3=int(E_3*N_1/E_1);
24 disp(N_3, '(b) Speed at 125% load(in rpm)=');

```

Scilab code Exa 2.28 Determine the value of resistance

```

1 //Caption:Determine the value of resistance
2 //Exa:2.28
3 clc;
4 clear;
5 close;
6 V=220; //in volts
7 R_a=0.1; //in ohms
8 N_1=800; //in rpm
9 N_2=520; //in rpm
10 I_a1=20; //in ampers
11 E_1=V-(I_a1*R_a); //in volts
12 E_2=N_2*E_1/N_1; //in volts
13 R_A=-(E_2-V+I_a1*R_a)/20;
14 disp(R_A, 'Additional resistance(in ohms)=');

```

Scilab code Exa 2.29 Determine the value of additional resistance at starting and at 1000rpm

```
1 //Caption:Determine the value of additional
   resistance (a)at starting (b)at 1000rpm
2 //Exa:2.29
3 clc;
4 clear;
5 close;
6 V=240;//in volts
7 R_a=0.3;//in ohms
8 N_1=1500;//in rpm
9 I_a=40;//in ampers
10 E=V-(I_a*R_a);//in volts
11 R_1=(V-I_a*R_a)/I_a;
12 disp(R_1,'(a) Additional resistance at starting (in
   ohms)=');
13 N_2=1000;//in rpm
14 E_2=N_2*E/N_1;//in volts
15 R_2=-(E_2-V+I_a*R_a)/I_a;
16 disp(R_2,'(b) Additional resistance at 1000 rpm (in
   ohms)=');
```

Scilab code Exa 2.30 Determine the speed at full load and speed at double full load and stalling torque in terms of full load torque

```
1 //Caption:Determine the (a) speed at full load (b)
   speed at double full load (c) stalling torque in
   terms of full load torque
2 //Exa:2.30
3 clc;
4 clear;
5 close;
6 V=250; //in volts
7 R_a=0.2; //in ohms
8 N_1=800; //in rpm
9 R_f=250; //in ohms
10 I_f=V/R_f; //in amperes
11 I=41; //in amperes
12 I_a1=I-I_f; //in amperes
13 E_1=V-(I_a1*R_a); //in volts
14 E_2=V-(I_a1*(R_a+2)); //in volts
15 N_2=E_2*N_1/E_1;
16 disp(N_2, '(a) Speed at full load (in rpm)=');
17 I_a2=I_a1*2; //in amperes
18 E_3=V-I_a2*(R_a+2); //in volts
19 N_3=E_3*N_1/E_1; //in rpm
20 disp(N_3, '(b) Speed at double full load (in rpm)=');
21 I_a0=V/(R_a+2);
22 r=I_a0/I_a1;
23 disp(r, '(c) stalling torque is (times full load
   torque) =')
```

Scilab code Exa 2.31 Determine the resistance to be inserted in series

```

1 //Caption:Determine the resistance to be inserted in
  series
2 //Exa:2.31
3 clc;
4 clear;
5 close;
6 V=200;//in volts
7 R_a=0.4;//in ohms
8 N_1=1000;//in rpm
9 N_2=800;//in rpm
10 I_a1=20;//in amperes
11 E_1=V-(I_a1*R_a);//in volts
12 I_a2=0.8*I_a1;//in amperes
13 E_2=N_2*I_a2*E_1/(N_1*I_a1);//in volts
14 R=-(E_2-193.6)/16;
15 disp(R,'the resistance to be inserted in series (in
  ohms)=')

```

Scilab code Exa 2.32 Determine the resistance to be inserted in series

```

1 //Caption:Determine the resistance to be inserted in
  series
2 //Exa:2.32
3 clc;
4 clear;
5 close;
6 V=500;//in volts
7 R_a=0.5;//in ohms
8 I_a1=60;//in amperes
9 E_1=V-(I_a1*R_a);//in volts
10 I_a2=sqrt(((0.75)^3)*I_a1^2);//in amperes

```

```

11 E_2=0.75*E_1*I_a2/I_a1;//in volts
12 R=-(E_2-480.5)/38.97;
13 disp(R, 'the resistance to be inserted in series (in
    ohms)=')

```

Scilab code Exa 2.33 Determine the output and efficiency when input current is 20A and 100A

```

1 //Caption:Determine the output and efficiency when
    input current is (a)20A (b)100A
2 //Exa:2.33
3 clc;
4 clear;
5 close;
6 V=500;//in volts
7 R_a=0.2;//in ohms
8 I_o=4;//in amperes
9 I_f=1;//in amperes
10 P_c=V*I_o-(((I_o-I_f)^2)*R_a);//in watts
11 I_1=20;///in amperes
12 P_i1=V*I_1;//in watts
13 P_a1=((I_1-I_f)^2)*R_a;//in watts
14 P_L1=P_c+P_a1;//in watts
15 P_o1=P_i1-P_L1;//in watts
16 disp(P_o1, '(a) Output (in watts)=');
17 disp(P_o1/P_i1*100, ' Efficiency (in %)=');
18 I_2=100;///in amperes
19 P_i2=V*I_2;//in watts
20 P_a2=((I_2-I_f)^2)*R_a;//in watts
21 P_L2=P_c+P_a2;//in watts
22 P_o2=P_i2-P_L2;//in watts

```



```

23 disp(P_o2, '(b) Output (in watts)=');
24 disp(P_o2/P_i2*100, ' Efficiency (in %)=');

```

Scilab code Exa 2.34 Determine the no load speed and Full load speed and Speed Regulation

```

1 //Caption:Determine the (a)no load speed (b)Full
  load speed (c)Speed Regulation
2 //Exa:2.34
3 clc;
4 clear;
5 close;
6 V=240;//in volts
7 V_b=2;//in volts
8 R_a=0.15;//in ohms
9 P=4;
10 Z=700;
11 Phy=0.06;//in Webers
12 A=P;
13 I_o=7;//in amperes
14 I_f=2;//in amperes
15 I=90;//in amperes
16 I_ao=I_o-I_f;//in amperes
17 E_bo=V-I_ao*R_a-V_b;//in volts
18 N_o=E_bo*60*A/(P*Phy*Z);//in rpm
19 disp(N_o, '(a)no load speed (in rpm)=');
20 I_a=I-I_f;//in amperes
21 E_b1=V-I_a*R_a-V_b;//in volts
22 N=E_b1*N_o/(E_bo*0.98);
23 disp(N, '(b)Full load speed (in rpm)=');
24 SR=100*(N_o-N)/N;

```

25 `disp(SR, '(c)Speed Regulation (in %)=')`;

Scilab code Exa 2.35 Determine the no load speed and Percentage reduction in flux per pole

```
1 //Caption:Determine the (a)no load speed (b)
  Percentage reduction in flux per pole
2 //Exa:2.35
3 clc;
4 clear;
5 close;
6 V=220; //in volts
7 V_b=1; //in volts
8 R_f=110; //in ohms
9 R_a=0.14; //in ohms
10 I_o=7; //in amperes
11 I_f=2; //in amperes
12 I=90; //in amperes
13 N_1=700; //in rpm
14 I_ao=I_o-I_f; //in amperes
15 E_bo=V-I_ao*R_a-V_b; //in volts
16 I=55; //in amperes
17 I_a1=I-I_f; //in amperes
18 E_b1=V-I_a1*R_a-V_b; //in volts
19 N_o=E_bo*N_1/E_b1;
20 disp(N_o, '(a)no load speed (in rpm) =');
21 I_a2=35; //in amperes
22 N_2=900; //in rpm
23 E_b2=V-I_a2*R_a-V_b; //in volts
24 Phy_r=E_b2*N_1/(E_b1*N_2);
25 R=(1-Phy_r)*100;
```

```
26 disp(R, '(b)Percentage reduction in flux per pole (in
    %=)');
```

Scilab code Exa 2.36 Determine the full load speed and Speed regulation and HP rating and Full load efficiency

```
1 //Caption:Determine the (a)full load speed (b)Speed
  regulation (c)HP rating (d)Full load efficiency
2 //Exa:2.36
3 clc;
4 clear;
5 close;
6 V=240;//in volts
7 R_f=120;//in ohms
8 R_a=0.25;//in ohms
9 I_1=60;//in amperes
10 I_f=V/R_f;//in amperes
11 I_a1=I_1-I_f;//in amperes
12 E_b1=V-I_a1*R_a;//in volts
13 N_o=1000;//in rpm
14 I=6;//in amperes
15 I_ao=I-I_f;//in amperes
16 E_bo=V-I_ao*R_a;//in volts
17 N_1=N_o*E_b1/E_bo;
18 disp(N_1, '(a)Full load speed (in rpm) =');
19 SR=100*(N_o-N_1)/N_o;
20 disp(SR, '(b)Speed regulation (in %) =');
21 P_o=E_b1*I_a1-(E_bo*I_ao);
22 HP=P_o/746;
23 disp(HP, '(c)HP rating (in HP)=');
24 P_i=V*I_1;
```

```
25 Eff=P_o*100/P_i;
26 disp(Eff, '(d) Efficiency (in %)=')
```

Scilab code Exa 2.37 Determine the speed Torque and Efficiency

```
1 //Caption:Determine the (a)speed (b)Torque (c)
  Efficiency
2 //Exa:2.37
3 clc;
4 clear;
5 close;
6 V=240;//in volts
7 P=4;
8 Phy=0.008;//in webers
9 Z=1000;
10 A=2;
11 R_f=240;//in ohms
12 R_a=0.4;//in ohms
13 I_1=25;//in amperes
14 I_f=V/R_f;//in amperes
15 I_a1=I_1-I_f;//in amperes
16 E_b=V-I_a1*R_a;//in volts
17 N=E_b*60*A/(P*Z*Phy);
18 disp(N, '(a)speed (in rpm) =');
19 P_m=E_b*I_a1;
20 T_g=(9.55*P_m)/N;
21 disp(T_g, '(b)Torque (in N-m)=');
22 P_f=P_m-800;
23 P_i=V*I_1;
24 Eff=P_f*100/P_i;
25 disp(Eff, '(c) Efficiency (in %)=')
```

Scilab code Exa 2.38 Determine the efficiency and power input

```
1 //Caption:Determine the efficiency and power input
2 //Exa:2.38
3 clc;
4 clear;
5 close;
6 P_out=20000;//in watts
7 P_in=23000;//in watts
8 V=250;//in volts
9 R_f=125;//in ohms
10 R_a=0.2;//in ohms
11 I_L=P_in/V;//in amperes
12 I_f=V/R_f;//in amperes
13 I_a1=I_L-I_f;//in amperes
14 P_cu=(I_a1^2)*R_a;
15 P_fcu=V*I_f;
16 P_tcu=P_cu+P_fcu;
17 P_fric=P_in-P_out-P_tcu;
18 P_o=12000;//in watts
19 P_m=P_o+P_fric
20 I_a2=53.85;
21 P_tcu2=((I_a2^2)*R_a)+250;
22 P_in_2=P_m+P_tcu2;
23 disp(P_in_2,'Power input (in watts)=');
24 Eff=P_o*100/P_in_2;
25 disp(Eff,'Efficiency (in %)=')
```

Scilab code Exa 2.39 Determine the efficiency armature current and max efficiency

```
1 //Caption:Determine the (a) efficiency (b) armature
   current (c) max efficiency
2 //Exa:2.39
3 clc;
4 clear;
5 close;
6 V=240; //in volts
7 R_f=240; //in ohms
8 R_a=0.6; //in ohms
9 I_o=5; //in amperes
10 I=18; //in amperes
11 I_f=V/R_f; //in amperes
12 I_ao=I_o-I_f;
13 I_a1=I-I_f;
14 E_bo=V-I_ao*R_a; //in volts
15 E_b1=V-I_a1*R_a; //in volts
16 P_dnL=E_bo*I_ao; //in watts
17 P_m=E_b1*I_a1; //in watts
18 P_o=P_m-P_dnL;
19 P_i=V*I; //in watts
20 Eff=P_o/P_i;
21 disp(Eff*100, '(a) Efficiency (in %)=')
22 I_a=sqrt((P_dnL+V*I)/R_a)
23 disp(I_a, '(b) Armature current (in Amperes)=')
24 E_b=V-I_a*R_a;
25 P_m2=E_b*I_a; //in watts
26 P_out=P_m2-P_dnL; //in watts
```

```

27 P_in=V*I_a; //in watts
28 Eff_m=P_out/P_in;
29 disp(Eff_m*100, '(c)Max Efficiency (in %)=')

```

Scilab code Exa 2.40 Calculate the Speed at full load and developed torque and Shaft power and Efficiency

```

1 //Caption: Calculate the (a)Speed at full load and
   developed torque (b)Shaft power (c)Efficiency
2 //Exa:2.40
3 clc;
4 clear;
5 close;
6 V=230; //in volts
7 R_a=0.4; //in ohms
8 I_a1=3.4; //in amperes
9 R_f=170; //in ohms
10 E_b1=V-I_a1*R_a;
11 I_f=V/R_f;
12 I_L=41; //in amperes
13 I_a2=I_L-I_f;
14 E_b2=214.142; //in volts
15 N_1=1000; //in rpm
16 N_2=N_1*E_b2/(E_b1*0.96); //in rpm
17 disp(N_2, '(a)Speed at full load (in rpm)=')
18 T_a=9.55*E_b2*I_a2/N_2;
19 disp(T_a, 'Torque Developed (in N-m)=')
20 P_r=E_b1*I_a1;
21 P_m=E_b2*I_a2;
22 P_f=P_m-P_r;
23 disp(P_f, '(b)Shaft Power (in watts)=')

```

```

24 P_in=V*I_L;
25 Eff=P_f/P_in;
26 disp(Eff*100, '(c) Efficiency (in %)=')

```

Scilab code Exa 2.41 Calculate the value of external resistance when the load torque is independent of speed and when the load torque is proportional to speed and the load torque varies as square of the speed

```

1 //Caption: Calculate the value of external resistance
   when (a) the load torque is independent of speed
   (b) the load torque is proportional to speed (c)
   the load torque varies as square of the speed
2 //Exa:2.41
3 clc;
4 clear;
5 close;
6 V=240; //in volts
7 R_a=0.25; //in ohms
8 R_f=120; //in ohms
9 I_f=V/R_f;
10 I_L=26; //in amperes
11 I_a=I_L-I_f;
12 N_1=1000; //in rpm
13 N_2=900; //in rpm
14 E_b1=V-I_a*R_a;
15 r=N_1/N_2;
16 R=(E_b1-(E_b1/r))/I_a;
17 disp(R, '(a) Value of external resistance when the
   load torque is independent of speed (in ohms)= ')
   ;
18 I_a2=I_a/r;

```



```

19 R1=(E_b1-(E_b1/r))/I_a2;
20 disp(R1,'(b) Value of external resistance when the
    load torque is proportional to speed (in ohms)= '
    );
21 I_a2_n=I_a/r^2;
22 R2=(E_b1-(E_b1/r))/I_a2_n;
23 disp(R2,'(a) Value of external resistance when the
    load torque is independent of speed (in ohms)= '
    );

```

Scilab code Exa 2.43 Find the efficiency of the motor

```

1 //Caption:Find the efficiency of the motor
2 //Exa:2.43
3 clc;
4 clear;
5 close;
6 V=240;//in volts
7 P=10000;//in watts
8 R_a=0.25;//in ohms
9 R_f=160;//in ohms
10 I_f=V/R_f;
11 I_L=5.2;//in amperes
12 I_ao=I_L-I_f;
13 W=V*I_ao-I_ao^2*R_a;
14 I_a=(V-sqrt(V^2-4*R_a*(P+W)))/(2*R_a);
15 P_in=P+W+I_a^2*R_a+I_f^2*R_f;
16 Eff=P/P_in;
17 disp(Eff*100,'Efficiency of the motor (in %)=')

```

Scilab code Exa 2.44 Find the armature voltage drop

```
1 //Caption:Find the armature voltage drop
2 //Exa:2.44
3 clc;
4 clear;
5 close;
6 V=440;//in volts
7 N_1=1000;//in rpm
8 N_2=1050;//in rpm
9 r=N_1/N_2;
10 V_drop=2*(V-V*r)
11 disp(V_drop,'Armature voltage drop (in volts)=')
```

Scilab code Exa 2.45 Find the no load speed

```
1 //Caption:Find the no load speed
2 //Exa:2.45
3 clc;
4 clear;
5 close;
6 V=220;//in volts
7 R_a=2.5;//in ohms
8 N_1=859;//in rpm
```

```

9 I_ao=0;
10 I_a=8; //in amperes
11 E_b1=V-I_a*R_a;
12 E_bo=V-I_ao*R_a;
13 N_o=N_1*E_bo/E_b1;
14 disp(N_o, 'No Load Speed (in RPM)=')

```

Scilab code Exa 2.46 Find the percentage reduction in feild flux and value of additional resistance

```

1 //Caption:Find the percentage reduction in feild
  flux and value of additional resistance
2 //Exa:2.46
3 clc;
4 clear;
5 close;
6 V=220; //in volts
7 R_a=0.2; //in ohms
8 R_f=110; //in ohms
9 N_1=700; //in rpm
10 N_2=900; //in rpm
11 T_a1=90; //in N-m
12 T_a2=70; //in N-m
13 I_1=27; //in amperes
14 I_f=V/R_f;
15 I_a1=I_1-I_f;
16 E_b1=V-I_a1*R_a;
17 x=(V+sqrt(V^2-4*276.43*4.168))/(2*276.43);
18 disp((1-x)*100, 'percentage reduction in feild flux (
  %)=');
19 I_f2=x*I_f;

```

```
20 R=(V-I_f2*R_f)/I_f2;
21 disp(R,'Value of additional resistance (in ohms)=')
```

Scilab code Exa 2.47 Find the new speed as a percentage of the original speed

```
1 //Caption:Find the new speed as a percentage of the
  original speed
2 //Exa:2.47
3 clc;
4 clear;
5 close;
6 V=400;//in volts
7 R_f=200;//in ohms
8 I_1=25;//in amperes
9 I_f=V/R_f;
10 I_a1=I_1-I_f;
11 x=(-V+sqrt(V^2+4*345*400))/(2*345);
12 disp(x*100,'New Speed is= ');
13 disp('percent of original speed')
```

Chapter 3

Single Phase Transformers

Scilab code Exa 3.1 Determine the number of turns of primary and secondary windings and emf per turn

```
1 //Caption:Determine the (a)number of turns of
   primary and secondary windings (b)emf per turn
2 //Exa:3.1
3 clc;
4 clear;
5 close;
6 A=500*10^-4;//in m^2
7 B_max=1.5;//in tesla
8 f=50;//in Hz
9 E_1=5000;//in volts
10 E_2=500;//in volts
11 S_f=0.85;//Stacking factor
12 N_1=int(E_1/(4.44*f*B_max*A*S_f));
13 disp(N_1,'(a)Number of turns in primary winding=');
14 N_2=int(E_2*N_1/E_1);
15 disp(N_2,'Number of turns in secondary winding=');
16 disp(E_1/N_1,'(b)Emf per turn (in Volts)=');
```

Scilab code Exa 3.2 Determine the number of turns of primary and secondary windings and cross section area of the core

```
1 //Caption:Determine the (a)number of turns of
   primary and secondary windings (b)cross section
   area of the core
2 //Exa:3.2
3 clc;
4 clear;
5 close;
6 B_max=1.4;//in tesla
7 f=50;//in Hz
8 E_1=660;//in volts
9 E_2=440;//in volts
10 E_T1=1.1;//in volts
11 N_1=int(E_1/E_T1);
12 disp(N_1,'(a)Number of turns in primary winding=');
13 N_2=int(E_2*N_1/E_1);
14 disp(N_2,'Number of turns in secondary winding=');
15 A=E_1/(4.44*f*N_1*B_max);
16 disp(A,'(b)Cross section area of the core (in m^2)=')
   );
```

Scilab code Exa 3.3 Determine the number of turns of primary and secondary windings

```
1 //Caption:Determine the number of turns of primary
   and secondary windings
2 //Exa:3.3
3 clc;
4 clear;
5 close;
6 Phy_max=7.82*10^-3;//in webers
7 f=50;//in Hz
8 E_1=5000;//in volts
9 E_2=500;//in volts
10 N_1=int(E_1/(4.44*f*Phy_max));
11 disp(N_1,'Number of turns in primary winding=');
12 N_2=int(E_2*N_1/E_1);
13 disp(N_2,'Number of turns in secondary winding=');
```

Scilab code Exa 3.4 Determine the Secondary voltage current flowing through windings and max value of flux

```
1 //Caption:Determine the (a)Secondary voltage (b)
   current flowing through windings (c)max value of
   flux
2 //Exa:3.4
3 clc;
4 clear;
5 close;
6 f=50;//in Hz
7 E_1=2500;//in volts
8 N_1=500;
```

```

9 N_2=100;
10 P=50*1000; //in watts
11 E_2=E_1*N_2/N_1;
12 disp(E_2, '(a)Secondary Voltage (in volts)=');
13 I_1=P/E_1;
14 disp(I_1, '(b)Primary current (in amperes)=');
15 I_2=P/E_2;
16 disp(I_2, 'Secondary current (in amperes)=');
17 Phy_max=E_1/(4.44*f*N_1);
18 disp(Phy_max, '(c)Max value of flux (in Wb)=')

```

Scilab code Exa 3.5 Determine the No load power factor iron loss component of current and magnetising component of current

```

1 //Caption:Determine the (a)No load power factor (b)
   iron loss component of current (c)magnetising
   component of current
2 //Exa:3.5
3 clc;
4 clear;
5 close;
6 f=50; //in Hz
7 W=80; //in watts
8 V=4400; //in volts
9 I=0.04; //in amperes
10 pf=W/(V*I);
11 disp(pf, '(a)No load power factor=');
12 I_w=I*pf;
13 disp(I_w, '(b)Iron loss component of current (in
   amperes)=');
14 I_m=I*sqrt(1-pf^2);

```



```
15 disp(I_m, '(c) Magnetising component of current (in  
    amperes)')
```

Scilab code Exa 3.6 Determine the No load input power magnetising component of current and no load power factor

```
1 //Caption:Determine the (a)No load input power (b)  
    magnetising component of current and no load  
    power factor  
2 //Exa:3.6  
3 clc;  
4 clear;  
5 close;  
6 f=50;//in Hz  
7 P=20*1000;//in watts  
8 E_1=2200;//in volts  
9 E_2=220;//in volts  
10 I=1.3;//in amperes  
11 I_w=0.5;//in amperes  
12 W=E_2*I_w;  
13 disp(W, '(a)No load input power (in watts)=')  
14 pf=I_w/I;  
15 disp(pf, '(b)No load power factor=');  
16 I_m=I*sqrt(1-pf^2);  
17 disp(I_m, ' Magnetising component of current (in  
    amperes)')
```

Scilab code Exa 3.7 Determine the Equivalent resistance leakage reactances and impedance referred to high voltage side and Equivalent resistance leakage reactances and impedance referred to high voltage side and Total copper loss of transformer

```

1 //Caption:Determine the (a)Equivalent resistance ,
   leakage reactances and impedance referred to high
   voltage side (b)Equivalent resistance ,leakage
   reactances and impedance referred to high voltage
   side (c)Total copper loss of transformer
2 //Exa:3.7
3 clc;
4 clear;
5 close;
6 f=50;//in Hz
7 P=30*1000;//in watts
8 E_1=3000;//in volts
9 E_2=300;//in volts
10 R_1=2.5;//in ohms
11 R_2=0.018;//in ohms
12 X_1=3.8;//in ohms
13 X_2=0.052;//in ohms
14 a=E_1/E_2;
15 R1=R_1+a^2*R_2;
16 X1=X_1+a^2*X_2;
17 Z1=sqrt(R1^2+X1^2);
18 disp(R1,'(a)Equivalent resistance referred to high
   voltage side (in ohms)=');
19 disp(X1,'   Equivalent reactance referred to high
   voltage side (in ohms)=');

```

```

20 disp(Z1, ' Equivalent impedance reffered to high
    voltage side (in ohms)=');
21 R2=R_1/a^2+R_2;
22 X2=X_1/a^2+X_2;
23 Z2=sqrt(R2^2+X2^2);
24 disp(R2, '(b)Equivalent resistance reffered to low
    voltage side (in ohms)=');
25 disp(X2, ' Equivalent reactance reffered to low
    voltage side (in ohms)=');
26 disp(Z2, ' Equivalent impedance reffered to low
    voltage side (in ohms)=');
27 I_1=P/E_1;
28 I_2=P/E_2;
29 P_cu=I_1^2*R1;
30 disp(P_cu, '(c)Total copper loss of transformer (in
    watts)=')

```

Scilab code Exa 3.8 Find the equivalent circuit parameters reffered to primary side

```

1 //Caption:Find the equivalent circuit parameters
  reffered to primary side
2 //Exa:3.8
3 clc;
4 clear;
5 close;
6 a=400/200;
7 I_o_Lv=2;//in amperes
8 I_o_Hv=I_o_Lv/a;//in amperes
9 V_o=400;//in volts
10 P_occ=90;//in watts

```

```

11 pf=P_occ/(V_o*I_o_Hv);
12 I_w=I_o_Hv*pf;
13 disp(I_w,'I_w (in Amperes)=');
14 I_m=I_o_Hv*sqrt(1-pf^2);
15 disp(I_m,'Magnetising current I_m (in Amperes)=');
16 R_o=V_o/I_w;
17 disp(R_o,'R_o (in ohms)=');
18 X_o=V_o/I_m;
19 disp(X_o,'Magnetizing reactance X_o (in ohms)=');
20 V_sc=20; //in volts
21 I_sc=10; //in amperes
22 P_sc=100; //in watts
23 Z_o1=V_sc/I_sc;
24 R_o1=P_sc/I_sc^2;
25 disp(R_o1,'Effective resistance reffered to primary
    side (in ohms)=');
26 X_o1=sqrt(Z_o1^2-R_o1^2);
27 disp(X_o1,'Effective reactance reffered to primary
    side (in ohms)=')

```

Scilab code Exa 3.9 Find the readings of transformers when it is connected for OC test and SC test

```

1 //Caption:Find the readings of transformers when it
    is connected for (a)OC test (b)SC test
2 //Exa:3.9
3 clc;
4 clear;
5 close;
6 V1=460; //in volts
7 V2=230; //in volts

```

```

8 a=V1/V2;
9 R1=0.4; //in ohms
10 R2=0.1; //in ohms
11 X1=0.5; //in ohms
12 X2=0.12; //in ohms
13 R_o=650; //in ohms
14 X_o=250; //in ohms
15 I_w=V1/R_o;
16 I_m=V1/X_o;
17 P_occ=V1*I_w;
18 disp('Readings of transformer for OC test');
19 disp(V1, 'Voltage Reading (in volts)=');
20 disp(sqrt(I_w^2+I_m^2), 'Current Reading (in Amperes)
    =');
21 disp(P_occ, 'Power output reading (in watts)=');
22 R_01=R1+a^2*R2;
23 X_01=X1+a^2*X2;
24 Z=sqrt(R_01^2+X_01^2);
25 I=4000/V1;
26 V_sc=I*Z;
27 P_sc=I^2*R_01;
28 disp('Readings of transformer for SC test');
29 disp(V_sc, 'Voltage Reading (in volts)=');
30 disp(I, 'Current Reading (in Amperes)=');
31 disp(P_sc, 'Power output reading (in watts)=');

```

Scilab code Exa 3.10 Find the equivalent circuit parameters of the transformer referred to LV side and also calculate the secondary voltage

```

1 //Caption:Find the equivalent circuit parameters of
    the transformer referred to LV side and also

```

```

        calculate the secondary voltage
2 //Exa:3.10
3 clc;
4 clear;
5 close;
6 V1=300; //in volts
7 I_o=0.8; //in amperes
8 W_o=70; //in watts
9 pf=W_o/(V1*I_o);
10 I_w=I_o*pf;
11 I_m=I_o*sqrt(1-pf^2);
12 R_0=V1/I_w;
13 X_0=V1/I_m;
14 a=300/600;
15 V_sc=20; //in volts
16 I_sc=12; //in amperes
17 P_sc=90; //in watts
18 Z_02=V_sc/I_sc;
19 R_02=P_sc/I_sc^2;
20 X_02=sqrt(Z_02^2-R_02^2);
21 R_01=a^2*R_02;
22 X_01=a^2*X_02;
23 I_2=6000/(600*0.8);
24 V2=I_2*(R_02*pf+X_02*sqrt(1-pf^2));
25 disp(R_0, 'R-O (in ohms)=');
26 disp(X_0, 'X-O Magnetising reactance (in ohms)=');
27 disp(R_01, 'Equivalent Resistance referred to LV Side
        (in ohms)=');
28 disp(X_01, 'Equivalent Reactance referred to LV Side
        (in ohms)');
29 disp(600-V2, 'Secondary Terminal Voltage (in volts)=')
    )

```

Scilab code Exa 3.11 Find the equivalent circuit parameters of the transformer referred to LV side and also calculate the efficiency

```
1 //Caption:Find the equivalent circuit parameters of
   the transformer referred to LV side and also
   calculate the efficiency
2 //Exa:3.11
3 clc;
4 clear;
5 close;
6 V1=200; //in volts
7 I_o=0.8; //in amperes
8 W_o=80; //in watts
9 pf=W_o/(V1*I_o);
10 I_w=I_o*pf;
11 I_m=I_o*sqrt(1-pf^2);
12 R_0=V1/I_w;
13 X_0=V1/I_m;
14 a=200/400;
15 V_sc=25; //in volts
16 I_sc=10; //in amperes
17 P_sc=90; //in watts
18 Z_02=V_sc/I_sc;
19 R_02=P_sc/I_sc^2;
20 X_02=sqrt(Z_02^2-R_02^2);
21 R_01=a^2*R_02;
22 X_01=a^2*X_02;
23 I_2=12;
24 I_1=I_2/a;
25 V2=sqrt((V1*pf+I_1*R_01)^2+(V1*sqrt(1-pf^2)+I_1*X_01
```

```

    )^2);
26 P_iron=80; //in watts
27 P_cu=(12/10)^2*90;
28 P_total=P_cu+P_iron;
29 Eff=6000*0.8/(6000*0.8+P_total);
30 disp(R_0, 'R_O (in ohms)=');
31 disp(X_0, 'X_O Magnetising reactance (in ohms)=');
32 disp(R_01, 'Equivalent Resistance referred to LV Side
    (in ohms)=');
33 disp(X_01, 'Equivalent Reactance referred to LV Side
    (in ohms)');
34 disp(Eff*100, 'Efficiency (in %)=')

```

Scilab code Exa 3.12 Calculate Efficiency of transformer Load KVA at which max efficiency occurs and max efficiency and voltage regulation

```

1 //Caption: Calculate (a) Efficiency of transformer (b)
    Load KVA at which max efficiency occurs and max
    efficiency (c) voltage regulation
2 //Exa:3.12
3 clc;
4 clear;
5 close;
6 V1=2000; //in volts
7 pf=0.8;
8 I1=10000/V1; //in amperes
9 P_iron=60; //in watts
10 V_sc=40; //in volts
11 I_sc=4; //in amperes
12 a=2000/200;
13 P_sc=70; //in watts

```



```

14 Z_01=V_sc/I_sc;
15 R_01=P_sc/I_sc^2;
16 X_01=sqrt(Z_01^2-R_01^2);
17 R_02=R_01/a^2;
18 X_02=X_01/a^2;
19 I2=I1*a/2; //At half load
20 Del_V=I2*(R_02*pf+X_02*sqrt(1-pf^2));
21 V2=200-Del_V;
22 P_o=V2*I2*pf; //in watts
23 P_cu=(2.5/4)^2*P_sc; //At half load
24 Eff=0.5*P_o/(0.5*P_o+P_iron+P_cu);
25 disp(Eff*100, '(a) Efficiency (in %)=');
26 I_1=sqrt(P_iron/R_01);
27 KVA_Load=10*I_1/5;
28 disp(KVA_Load, '(b) Load KVA at which max efficiency
    occurs=');
29 Eff_max=P_o/(P_o+P_iron+P_iron);
30 disp(Eff_max*100, '    Max Efficiency (in %)=');
31 I_2=50; //at full load
32 VR=(I_2*(R_02*pf-X_02*sqrt(1-pf^2)))/200;
33 disp(VR*100, '(c) Voltage Regulation (in %)=')

```

Scilab code Exa 3.13 Determine the KVA rating of auto transformer with additive and subtractive polarity also find the efficiency at full load and unity power factor

```

1 //Caption:Determine the KVA rating of auto
    transformer with additive and subtractive
    polarity also find the efficiency at full load
    and unity power factor
2 //Exa:3.13

```

```

3  clc;
4  clear;
5  close;
6  P=120*1000; //in watts
7  V1=2400; //in volts
8  V2=240; //in volts
9  I1=P/V1; //in amperes
10 I2=P/V2; //in amperes
11 KVA_1=V1*(I1+I2)/1000;
12 P_trans=V2*I2/1000;
13 P_cond_1=KVA_1-P_trans;
14 P_loss_1=((1/0.98)-1)^2*P_trans;
15 Eff_a=1-(P_loss_1/KVA_1)
16 disp(KVA_1, 'KVA Rating of transformer with additive
    polarity (in KVA)=');
17 disp(Eff_a*100, 'Efficiency of auto transformer with
    additive polarity (in %)=');
18 KVA_2=V1*(I2-I1)/1000;
19 P_trans=V2*I2/1000;
20 P_cond_2=KVA_2-P_trans;
21 P_loss=((1/0.98)-1)^2*P_trans;
22 Eff_s=1-(P_loss/KVA_2)
23 disp(KVA_2, 'KVA Rating of transformer with
    subtractive polarity (in KVA)=');
24 disp(Eff_s*100, 'Efficiency of auto transformer with
    subtractive polarity (in %)=');

```

Scilab code Exa 3.14 Calculate the parameters referred to LV Side and also find the voltage regulation at full load and efficiency of transformer at full load and half load

```

1 //Caption: Calculate the parameters reffered to LV
   Side and also find the voltage regulation at full
   load and efficiency of transformer at full load
   and half load at 0.8pf lagging
2 //Exa:3.14
3 clc;
4 clear;
5 close;
6 a=0.5;
7 V1=200; //in volts
8 I_o=0.8; //in amperes
9 W_o=75; //in watts
10 pf=W_o/(V1*I_o);
11 pf2=0.8;
12 R_0=V1/(I_o*pf);
13 X_0=V1/(I_o*sqrt(1-pf^2));
14 V_sc=20; //in volts
15 I_sc=10; //in amperes
16 P_sc=90; //in watts
17 Z_02=V_sc/I_sc;
18 R_02=P_sc/I_sc^2;
19 X_02=sqrt(Z_02^2-R_02^2);
20 R_01=a^2*R_02;
21 X_01=a^2*X_02;
22 I_2=4000/400; //in amperes
23 VR=I_2*(R_02*pf2+X_02*sqrt(1-pf2^2))/400;
24 disp(R_0, 'R_0 (in ohms)=');
25 disp(X_0, 'X_0 Magnetising reactance (in ohms)=');
26 disp(R_01, 'Equivalent Resistance reffered to LV Side
   (in ohms)=');
27 disp(X_01, 'Equivalent Reactance reffered to LV Side
   (in ohms)');
28 disp(VR*100, 'Voltage Regulation at full load (in %)=
   ');
29 P_o=(400-I_2*(R_02*pf2+X_02*sqrt(1-pf2^2)))*I_2*pf2;
30 P_i=75; //in watts
31 P_cu=P_sc;
32 P_cu_h=0.5^2*P_cu;

```

```

33 Eff=P_o/(P_o+P_i+P_cu);
34 disp(Eff*100,'Efficiency at full load (in %)=');
35 P_o_h=(400-I_2*0.5*(R_02*pf2+X_02*sqrt(1-pf2^2)))*
    I_2*0.5*pf2;
36 Eff_h=P_o_h/(P_o_h+P_i+P_cu_h);
37 disp(Eff_h*100,'Efficiency at half load (in %)=');

```

Scilab code Exa 3.15 Calculate the circuit parameters referred to LV Side and also calculate the regulation and efficiency of transformer at full load and half load

```

1 //Caption: Calculate the circuit parameters referred
    to LV Side and also calculate the regulation and
    efficiency of transformer at full load and half
    load at 0.8 pf
2 //Exa:3.15
3 clc;
4 clear;
5 close;
6 a=0.5;
7 V1=250;//in volts
8 I_o=1.2;//in amperes
9 W_o=80;//in watts
10 pf=W_o/(V1*I_o);
11 pf2=0.8;
12 R_0=V1/(I_o*pf);
13 X_0=V1/(I_o*sqrt(1-pf^2));
14 V_sc=25;//in volts
15 I_sc=10;//in amperes
16 P_sc=95;//in watts
17 Z_02=V_sc/I_sc;

```

```

18 R_02=P_sc/I_sc^2;
19 X_02=sqrt(Z_02^2-R_02^2);
20 R_01=a^2*R_02;
21 X_01=a^2*X_02;
22 I_2=6000/500;//in amperes
23 VR=I_2*(R_02*pf2+X_02*sqrt(1-pf2^2))/500;
24 VR_h=0.5*I_2*(R_02*pf2+X_02*sqrt(1-pf2^2))/500;
25 disp(R_0,'R_0 (in ohms)=');
26 disp(X_0,'X_0 Magnetising reactance (in ohms)=');
27 disp(R_01,'Equivalent Resistance referred to LV Side
    (in ohms)=');
28 disp(X_01,'Equivalent Reactance referred to LV Side
    (in ohms)');
29 disp(VR*100,'Voltage Regulation at full load (in %)=
    ');
30 disp(VR_h*100,'Voltage Regulation at half load (in %
    )=');
31 P_o=(500-I_2*(R_02*pf2+X_02*sqrt(1-pf2^2)))*I_2*pf2;
32 P_i=80;//in watts
33 P_cu=(12/10)^2*P_sc;
34 P_cu_h=0.5^2*P_cu;
35 Eff=P_o/(P_o+P_i+P_cu);
36 disp(Eff*100,'Efficiency at full load (in %)=');
37 P_o_h=(500-I_2*0.5*(R_02*pf2+X_02*sqrt(1-pf2^2)))*
    I_2*0.5*pf2;
38 Eff_h=P_o_h/(P_o_h+P_i+P_cu_h);
39 disp(Eff_h*100,'Efficiency at half load (in %)=');

```

Scilab code Exa 3.16 Find the efficiency of transformer at full load and 75 percent of full load

```

1 //Caption:Find the efficiency of transformer at full
   load and 75 percent of full load (a)at unity
   power factor (b)0.8 power factor
2 //Exa:3.16
3 clc;
4 clear;
5 close;
6 I_2=200;//in amperes
7 R_02=0.008;//in ohms
8 x=0.75;
9 P_cu=x^2*I_2^2*R_02;//in watts
10 P_i=190;//in watts
11 KVA=40;
12 P_o=40*1000;//in watts
13 Eff=P_o/(P_o+P_i+I_2^2*R_02);
14 Eff_2=KVA*1000*0.8/(KVA*1000*0.8+P_i+I_2^2*R_02);
15 disp(Eff*100,'(a)Efficiency of transformer at full
   load and at unity power factor (in %)=');
16 disp(Eff_2*100,'(b)Efficiency of transformer at full
   load and at 0.8 power factor (in %)=');
17 Eff_3=x*P_o/(x*P_o+P_i+P_cu);
18 Eff_4=x*P_o*0.8/(x*0.8*P_o+P_i+P_cu);
19 disp(Eff_3*100,'(a)Efficiency of transformer at 75%
   of load and at unity power factor (in %)=');
20 disp(Eff_4*100,'(b)Efficiency of transformer at 75%
   of load and at 0.8 power factor (in %)=');

```

Scilab code Exa 3.17 Determine the Load at which max efficiency occurs and value of max efficiency and New core loss and Cu loss

```

1 //Caption:Determine the (a)Load at which max

```

```

    efficiency occurs and value of max efficiency (b)
    New core loss and Cu loss
2 //Exa:3.17
3 clc;
4 clear;
5 close;
6 KVA=20;
7 P_i=250;//in watts
8 P_cu=500;//in watts
9 x=sqrt(P_i/P_cu);
10 disp(x*100,'(a)Max efficiency will occur at');
11 disp('Percent of full load');
12 P_o=x*KVA*1000;
13 Eff=P_o/(P_o+P_i+P_cu);
14 disp(Eff*100,'Maximum Efficiency (in %)=');
15 P_cu_n=(P_i+P_cu)/(0.85^2+1);
16 P_i_n=P_i+P_cu-P_cu_n;
17 disp(P_i_n,'(b)Core Loss (in watts)=');
18 disp(P_cu_n,'Copper Loss (in watts)=')

```

Scilab code Exa 3.18 Calculate the secondary current at which max efficiency will occur and also calculate the max efficiency

```

1 //Caption:Calculate the secondary current at which
    max efficiency will occur and also calculate the
    max efficiency at 0.8pf lagging
2 //Exa:3.18
3 clc;
4 clear;
5 close;
6 a=1000/200;

```

```

7 R_1=0.25; //in ohms
8 R_2=0.018; //in ohms
9 R_02=R_2+R_1/a^2;
10 P_i=240; //in watts
11 I_2=sqrt(P_i/R_2);
12 disp(I_2, 'The secondary current at which max
    efficiency will occur (in Amperes)=');
13 P_o=200*I_2*0.8; //in watts
14 P_t=2*P_i; //in watts
15 Eff=P_o/(P_o+P_t);
16 disp(Eff*100, 'Max efficiency at 0.8pf lagging (in %)=
    ')

```

Scilab code Exa 3.19 Find the iron loss copper loss at full load Load KVA at which maximum efficiency occurs and maximum efficiency of transformer

```

1 //Caption:Find the (a)iron loss (b)copper loss at
    full load (c)Load KVA at which maximum efficiency
    occurs (d)maximum efficiency of transformer at
    0.8pf lagging
2 //Exa:3.19
3 clc;
4 clear;
5 close;
6 KVA=150;
7 pf=0.8;
8 Eff=0.96;
9 P_o=KVA*1000*pf; //in watts
10 P_cu=P_o*((1/Eff)-1)*(1-0.5)*4/3;
11 P_i=4999.9-P_cu;
12 disp(P_i, '(a)Iron Loss (in watts)=');

```



```

13 disp(P_cu, '(b)Copper Loss at full load (in watts)=')
    ;
14 x=sqrt(P_i/P_cu);
15 disp(x*KVA, '(c)Load KVA at which maximum efficiency
    occurs (in KVA)=');
16 Eff_max=x*KVA*1000*0.8/(x*KVA*1000*0.8+2*P_i);
17 disp(Eff_max*100, '(d)maximum efficiency of
    transformer at 0.8 pf lagging(in %)=')

```

Scilab code Exa 3.22 Calculate Efficiency at full load and half load

```

1 //Caption: Calculate (a) Efficiency at full load and
    at unity power factor (b) Efficiency at half load
    and 0.8 power factor (c) Efficiency at 75 percent
    of load and 0.7 power factor (d) load KVA at which
    maximum efficiency will occur (e) maximum
    efficiency at 0.85 power factor
2 //Exa:3.22
3 clc;
4 clear;
5 close;
6 KVA=100;
7 P_cu=1200; //in watts
8 P_i=960; //in watts
9 x1=1;
10 pf1=1;
11 P_o_1=x1*KVA*pf1*1000;
12 Eff_1=P_o_1/(P_o_1+P_i+x1^2*P_cu);
13 disp(Eff_1*100, '(a) Efficiency at full load and at
    unity power factor (in %)=');
14 x2=0.5;

```

```

15 pf2=0.8;
16 P_o_2=x2*KVA*1000*pf2;
17 Eff_2=P_o_2/(P_o_2+P_i+x2^2*P_cu);
18 disp(Eff_2*100,'(b) Efficiency at half load and at
    0.8 power factor (in %)=');
19 x3=0.75;
20 pf3=0.7;
21 P_o_3=x3*KVA*1000*pf3;
22 Eff_3=P_o_3/(P_o_3+P_i+x3^2*P_cu);
23 disp(Eff_3*100,'(c) Efficiency at 75 percent of load
    and 0.7 power factor(in %)=');
24 KVA_max=KVA*sqrt(P_i/P_cu);
25 disp(KVA_max,'(d)load KVA at which maximum
    efficiency will occur (in KVA)=');
26 Eff_max=KVA_max*1000*0.85/(KVA_max*1000*0.85+2*P_i);
27 disp(Eff_max*100,'(e)maximum efficiency at 0.85
    power factor(in %)=')

```

Scilab code Exa 3.23 Calculate the core loss and copper loss and also find the value of load current at which max efficiency will be attained

```

1 //Caption: Calculate the core loss and copper loss
    and also find the value of load current at which
    max efficiency will be attained
2 //Exa:3.23
3 clc;
4 clear;
5 close;
6 KVA=100;
7 V2=11000;//in volts
8 x1=1;

```

```

9 x2=0.5;
10 pf1=0.8;
11 pf2=1;
12 Eff_1=0.985;
13 Eff_2=0.99;
14 P_cu=(KVA*1000*x1*pf1*((1/Eff_1)-1)-x2*KVA*1000*((1/
    Eff_2)-1))*(4/3); // in watts
15 P_i=1218-P_cu; // in watts
16 I_f1=KVA*1000/V2;
17 I_2=I_f1*sqrt(P_i/P_cu);
18 disp(P_cu, 'Copper loss (in watts)=');
19 disp(P_i, 'Core loss (in watts)=');
20 disp(I_2, 'Load current (in amperes)=')

```

Scilab code Exa 3.24 Calculate the efficiency of the transformer at 75 percent of full load and maximum efficiency

```

1 //Caption: Calculate the efficiency of the
    transformer at 75 percent of full load and
    maximum efficiency
2 //Exa:3.24
3 clc;
4 clear;
5 close;
6 P_o=500; //in watts
7 Eff_f1=0.9;
8 Eff_h1=0.9;
9 P_cu=((P_o-0.5*P_o)/Eff_f1)-0.5*P_o)*4/3; // in
    watts
10 P_i=0.5*P_cu; // in watts
11 Eff=P_o*0.75/(P_o*0.75+P_i+0.75^2*P_cu);

```

```

12 disp(Eff*100, 'Efficiency of transformer at 75
    percent of full load(in %)=');
13 P_o_max=P_o*sqrt(P_i/P_cu);
14 Eff_max=P_o_max/(P_o_max+P_i+P_i);
15 disp(Eff_max*100, 'Maximum efficiency (in %)=')

```

Scilab code Exa 3.25 Calculate the efficiency of the transformer on full load and half load at unity power factor

```

1 //Caption:Calculate the efficiency of the
    transformer on full load and half load at unity
    power factor
2 //Exa:3.25
3 clc;
4 clear;
5 close;
6 KVA=100;
7 P_i=1300;//in watts
8 P_cu=1200;//in watts
9 pf=1;
10 Eff_fl=KVA*1000*pf/(KVA*1000*pf+P_i+P_cu);
11 disp(Eff_fl*100, 'Efficiency of transformer at full
    load (in %)=');
12 Eff_hl=KVA*1000*0.5*pf/(KVA*0.5*1000*pf+P_i+0.25*
    P_cu);
13 disp(Eff_hl*100, 'Efficiency of transformer at half
    load (in %)=');

```

Scilab code Exa 3.26 Find the voltage regulation

```
1 //Caption:Find the voltage regulation
2 //Exa:3.26
3 clc;
4 clear;
5 close;
6 KVA=100;
7 Eff_max=0.98;
8 x=0.8;
9 pf=0.8;
10 P_o=x*KVA*1000*pf;//in watts
11 P_i=(P_o-P_o*Eff_max)/(2*Eff_max);//in watts
12 P_cu=P_i/x^2;
13 R_equ=P_cu/(KVA*1000);
14 Z_equ=0.05;
15 X_equ=sqrt(Z_equ^2-R_equ^2);
16 VR=R_equ*pf+X_equ*sqrt(1-pf^2);
17 disp(VR*100, 'Voltage Regulation (in %)=')
```

Scilab code Exa 3.27 Calculate the percentage resistance and reactance drops and the percentage of full load at which max efficiency will occur

```

1 //Caption:Calculate the percentage resistance and
    reactance drops and the percentage of full load
    at which max efficiency will occur
2 //Exa:3.27
3 clc;
4 clear;
5 close;
6 KVA=20;
7 V1=1100;//in volts
8 V2=220;//in volts
9 a=V1/V2;
10 P_i=175;//in watts
11 R1=0.25;//in ohms
12 R2=0.012;//in ohms
13 X1=1.1;//in ohms
14 X2=0.055;//in ohms
15 R_02=R2+R1/a^2;
16 X_02=X2+X1/a^2;
17 I2=KVA*1000/V2;
18 V_r=I2*R_02*100/V2;
19 disp(V_r,'Percentage Resistance drop (in %)=');
20 V_re=I2*X_02*100/V2;
21 disp(V_re,'Percentage Reactance drop (in %)=');
22 P_cu=I2^2*R_02;
23 x=sqrt(P_i/P_cu);
24 disp(x*100,'Max Efficiency will occur at');
25 disp('percent of full load');

```

Scilab code Exa 3.28 Find the voltage regulation

```

1 //Caption:Find the voltage regulation

```

```

2 //Exa:3.28
3 clc;
4 clear;
5 close;
6 KVA=500;
7 V2=500;//in volts
8 x=0.75;
9 pf=1;
10 Eff_max=0.97;
11 P_i=(KVA*x*1000*pf-KVA*x*1000*pf*Eff_max)/(2*Eff_max
    );//in watts
12 P_cu=P_i/x^2;
13 R_equ=P_cu/(KVA*1000);
14 X_equ=sqrt(0.1^2-R_equ^2);//in ohms
15 VR=R_equ*0.8+X_equ*0.6;
16 disp(VR*100,'Voltage Regulation (in %)=')

```

Scilab code Exa 3.29 Calculate the value of iron loss and copper loss which will give max efficiency and also the max efficiency

```

1 //Caption:Calculate the value of iron loss and
    copper loss which will give max efficiency and
    also the max efficiency
2 //Exa:3.29
3 clc;
4 clear;
5 close;
6 KVA=25;
7 P_iron=350;//in watts
8 //For max efficiency P_iron=P_cu
9 P_cu=P_iron;

```

```

10 disp(P_iron, 'Iron loss (in watts)=');
11 disp(P_cu, 'Copper Loss (in watts)=');
12 Eff=KVA*1000/(KVA*1000+P_iron+P_cu);
13 disp(Eff*100, 'Maximum Efficiency (in %)=');

```

Scilab code Exa 3.30 Find the Efficiency and voltage regulation of transformer

```

1 //Caption:Find the Efficiency and voltage regulation
  of transformer
2 //Exa:3.30
3 clc;
4 clear;
5 close;
6 P_i=100; //in watts
7 V2=400; //in volts
8 P_sc=200; //in watts
9 I_2=11.4; //in amperes
10 R_02=P_sc/I_2^2; //in ohms
11 KVA=5;
12 I_2f1=KVA*1000/V2;
13 P_cu=I_2f1^2*R_02;
14 pf=0.9;
15 Eff=KVA*1000*pf/(KVA*1000*pf+P_cu+P_i);
16 disp(Eff*100, 'Efficiency (in %)=');
17 V_2sc=40; //in volts
18 Z_02=V_2sc/I_2;
19 X_02=sqrt(Z_02^2-R_02^2);
20 VR=I_2f1*(R_02*pf+X_02*sqrt(1-pf^2))/V2;
21 disp(VR*100, 'Voltage Regulation (in %)=')

```

Chapter 4

Three Phase Transformers

Scilab code Exa 4.1 Find the value of line current

```
1 //Caption:Find the value of line current
2 //Exa:4.1
3 clc;
4 clear;
5 close;
6 a=2200/200;//transformation ratio
7 P=450*1000;//in watts
8 pf=0.85;
9 V_s=200;//in volts
10 I_2=P/(pf*V_s);//in amperes
11 I_1=1.15*I_2/a;
12 disp(I_1,'Value of line currents (in Amperes)=')
```

Scilab code Exa 4.2 Find the value of line current

```

1 //Caption:Find the value of line current
2 //Exa:4.2
3 clc;
4 clear;
5 close;
6 a=2200/200;//transformation ratio
7 P_1=400*1000;//in watts
8 P_2=500*1000;//in watts
9 pf=0.8;
10 V_s=200;//in volts
11 I_2=P_1/(pf*V_s);//in amperes
12 I_1=1.15*I_2/a;
13 I_1T=I_1/2;
14 I_2M=P_2/(pf*V_s*a);
15 I_p=sqrt((I_1T^2)+(I_2M^2));
16 disp(I_p,'Value of line current (in Amperes)=')

```

Scilab code Exa 4.3 Determine the efficiency of transformer

```

1 //Caption:Determine the efficiency of transformer at
   (a)full load and 0.85pf (b)75 percent of full
   load and unity pf (c)max efficieny at unity pf
2 //Exa:4.3
3 clc;
4 clear;
5 close;
6 P=100*1000;//in watts
7 P_iron=1500;//in watts
8 x=0.8;
9 P_cu=1500/x^2;//in watts
10 pf=0.8;

```

```

11 a=5000/400; //transformation ratio
12 P_t=P_iron+P_cu;
13 P_o=0.85*P; //in watts
14 Eff=P_o/(P_o+P_t);
15 disp(Eff*100, '(a) Efficiency at full load and 0.85 pf
      (in %)=');
16 P_cu_1=0.75*P_cu; //in watts
17 P_t_1=P_cu_1+P_iron; //in watts
18 P_o_1=0.75*P;
19 Eff_1=P_o_1/(P_o_1+P_t_1);
20 disp(Eff_1*100, '(b) Efficiency at 75 percent of full
      load and unity pf(in %)=');
21 P_t_2=2*P_iron;
22 P_o_2=P;
23 Eff_2=P_o_2/(P_o_2+P_t_2);
24 disp(Eff_2*100, '(c)max efficieny at unity pf(in %)=
      ');

```

Scilab code Exa 4.4 Find the value of line voltage and line current and output

```

1 //Caption:Find the value of line voltage ,line
      current ,and output when the transformer winding
      is connected as (a) Star-delta (b)delta-star
2 //Exa:4.4
3 clc;
4 clear;
5 close;
6 a=10; //transformation ratio
7 V_s=3300; //in volts
8 I_1=10; //in amperes

```

```

 9 V_1=V_s/sqrt(3);
10 V_2=V_1/a;
11 I_2=sqrt(3)*a*I_1;
12 P_o=sqrt(3)*V_2*I_2;
13 disp("For Star-Delta Configuration")
14 disp(V_2,'Line voltage (in volts)=');
15 disp(I_2,'Line current (in amperes)=');
16 disp(P_o,'Output (in watts)=');
17 V_2p=V_s/a;
18 V_2L=sqrt(3)*V_2p;
19 I_2L=I_1*a/sqrt(3);
20 P_o2=sqrt(3)*V_2*I_2;
21 disp("For Delta-Star Configuration")
22 disp(V_2L,'Line voltage (in volts)=');
23 disp(I_2L,'Line current (in amperes)=');
24 disp(P_o2,'Output (in watts)=');

```

Scilab code Exa 4.5 Find the Efficiency

```

1 //Caption:Find the Efficiency
2 //Exa:4.5
3 clc;
4 clear;
5 close;
6 P=1200*1000;//in watts
7 R_1=2;//in ohms
8 R_2=0.03;//in ohms
9 P_iron=20000;//in watts
10 V_1p=6600;//in volts
11 V_2p=1100/sqrt(3);//in volts
12 a=V_1p/V_2p;

```

```

13 R_o2=R_2+(R_1/a^2); //in ohms
14 I_2p=P/(sqrt(3)*1100); //in amperes
15 P_cu=3*R_o2*I_2p^2;
16 P_t=P_iron+P_cu;
17 P_o=0.9*P; //in watts
18 Eff=P_o/(P_o+P_t);
19 disp(Eff*100, 'Efficiency (in %)=')

```

Scilab code Exa 4.6 Find the percentage resistance and reactance drop and efficiency and voltage regulation

```

1 //Caption:Find the percentage resistance ,reactance
  drop,efficiency and voltage regulation
2 //Exa:4.6
3 clc;
4 clear;
5 close;
6 P=1500*1000; //in watts
7 phy=acosd(0.8);
8 V_1P=300; //in volts
9 V_1L=6600; //in volts
10 I_1P=131.21/sqrt(3);
11 Z_1=V_1P/I_1P; //in ohms
12 R_1=30*1000/(3*I_1P^2);
13 X_1=sqrt((Z_1^2)-(R_1^2));
14 R=I_1P*R_1*100/V_1L;
15 X=I_1P*X_1*100/V_1L;
16 disp(R, '% Resistance drop (in %)=');
17 disp(X, '% Reactance drop (in %)=');
18 VR=(R*cosd(phy))+(X*sind(phy));
19 disp(VR, 'Voltage regulation (in %)=')

```

```

20 I_1_FL=P/(sqrt(3)*V_1L);
21 P_t=(30+25)*1000;//in watts
22 P_o=P*0.8;//in watts
23 Eff=P_o/(P_o+P_t);
24 disp(Eff*100,'Efficiency (in %)=')

```

Scilab code Exa 4.7 Determine the KVA Load and Percentage rated load and Total KVA Rating and Ratio of star bank to delta bank transformer rating and percentage increase in load

```

1 //Caption:Determine the (a)KVA Load (b)Percentage
   rated load (c)Total KVA Rating (d)Ratio of star-
   star bank to delta-delta bank transformer rating
   (e)% increase in load
2 //Exa:4.7
3 clc;
4 clear;
5 close;
6 KVA=25;
7 KVA_s=50/sqrt(3);
8 disp(KVA_s,'(a)KVA Load supplied by each transformer
   (in KVA)=');
9 r=KVA_s/KVA;
10 disp(r,'(b)Percent of rated load (in %)=');
11 KVA_t=2*25*0.866;
12 disp(KVA_t,'(c)Total KVA rating (in KVA)=');
13 ratio=KVA_t/75;
14 disp(ratio,'(d)Ratio=');
15 KVA_s2=50/3;
16 Inc=KVA_s/KVA_s2;
17 disp(Inc*100,'(e)Increase in load (in %)=')

```

Scilab code Exa 4.8 Determine the Current flowing in various sections and Power transformed and Power conducted directly

```
1 //Caption:Determine the (a)Current flowing in
   various sections (b)Power transformed (c)Power
   conducted directly
2 //Exa:4.8
3 clc;
4 clear;
5 close;
6 P=400*1000;//in watts
7 pf=0.8;
8 V_1=550;//in volts
9 V_2=440;//in volts
10 I_2=P/(sqrt(3)*V_2*pf);// in amperes
11 I_1=I_2*V_2/V_1;//in amperes
12 I=I_2-I_1;
13 disp(I, '(a)Currents in sections Oa,Ob and Oc (in
   amperes)=');
14 disp(I_1, 'Currents in sections Aa,Bb and Cc (in
   amperes)=');
15 P_trans=P*(1-(V_2/V_1));
16 disp(P_trans/1000, '(b)Power transformed by
   transformer action (in Kw)=');
17 P_cond=P-P_trans;
18 disp(P_cond/1000, '(c)Power Conducted directly (in Kw)
   =')
```
